

MEDIA RELEASE

29 November 2015

A fatality has occurred involving a delivery driver at the Tarong power stations earlier this morning.

Queensland Police and emergency services are in attendance.

Stanwell and UGL are devastated for the family, friends and work mates of the delivery driver.

Stanwell and UGL will do everything it can to assist the family, its employees and contractors during this time.

Counselling support is being arranged for those directly and indirectly involved.

Stanwell and UGL are working closely with all relevant authorities to investigate this tragedy.

Further information will be provided as it becomes available.

All media enquiries should be directed to Queensland Police Media.

Background:

UGL Limited (UGL) provides facility management, overhaul, asset and maintenance management (FOAMM) services at the Tarong power stations.